

Inspection Photos
Operator: Logos
API: 067-05411
Date: 6/3/2021




Photo 1. View of project area from the northwestern corner facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Revegetation is progressing with western wheatgrass, smooth brome, and crested wheatgrass. Revegetation at final reclamation will need to use a native seed mix representative of the reference area.



Photos 3. View of the southern project area from the southwestern corner facing eastward.



Photos 4. View of musk thistles within the western project area. Approximately 30 individuals observed.



Photos 5. View of reference area comprised of big sagebrush and black sagebrush shrubland with scattered pinyon and juniper trees, and squirreltail, western wheatgrass, mat penstemon in the understory.