

Inspection Photos

API: 073-06311

Operator: NIGHTHAWK PRODUCTION LLC

Inspection Date: 6/2/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast toward the location. The perimeter fence remains around the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06311 | Date: 6/2/2021

Inspection Photos



Photo 2. Facing northeast at the location. There is desirable vegetation establishment throughout most areas of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06311 | Date: 6/2/2021

Inspection Photos



Photo 3. Center of the location facing north.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06311 | Date: 6/2/2021

Inspection Photos



Photo 4. Center of the location facing east. There is desirable vegetation establishment throughout most areas of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06311 | Date: 6/2/2021

Inspection Photos



Photo 5. North side of the location facing this area consists of mostly undesirable weeds.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06311 | Date: 6/2/2021

Inspection Photos



Photo 6. This 60'x30' area at the center of the location does not have vegetation growth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06311 | Date: 6/2/2021