

Inspection Photos
Location Name: Tom L Russell #2
Location ID: 318279



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: Tom L Russell #2
Location ID: 318279



Photo 3 Pump Jack



Photo 4 ancillary equipment



Inspection Photos
Location Name: Tom L Russell #2
Location ID: 318279



Photo 5 TB sign



Photo 6 TB

Inspection Photos
Location Name: Tom L Russell #2
Location ID: 318279



Photo 7 Horizontal Heated Separator



Photo 8 Heater treater



Inspection Photos
Location Name: Tom L Russell #2
Location ID: 318279



Photo 9 stained soil inside Horizontal Heated Separator housing



Photo 10 Stained soil inside of Heater treater housing

Inspection Photos
Location Name: Tom L Russell #2
Location ID: 318279



Photo 11 Dead weeds throughout PW/flow line area



Photo 12 Dead weeds throughout PW/flow line area



Inspection Photos
Location Name: Tom L Russell #2
Location ID: 318279



Photo 13 Dead weeds throughout ROW




Photo 14 unused Gas Meter Run

Inspection Photos
Location Name: Tom L Russell #2
Location ID: 318279



Photo 15 Dead weeds around TB fencing



Photo 16 Dead weeds around TB fencing