

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/08/2021

Submitted Date:

06/09/2021

Document Number:

696104635

FIELD INSPECTION FORM

Loc ID: 327512 Inspector Name: Evins, Bret On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

12 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246993	WELL	TA	10/01/2019	OW	123-14790	STATE A36-9	TA

General Comment:

This is a WELL inspection.
Well(s): 1: Temporarily Abandoned | TA.
Battery: Inactive | Shut-down.

Centralized Battery serves 4 Location IDs (302425, 310494, 310631, 327512).
(Well(s): 1: Shut-In | SI ; 3: Temporarily Abandoned | TA).

Refer to Field Inspection Report doc. #696104629 and/or Location ID #302425 for Battery / Facility, Equipment info.

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type			
Comment:	Refer to Field Inspection Report doc. #696104629 and/or Location ID #302425 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type			
Comment:	Refer to Field Inspection Report doc. #696104629 and/or Location ID #302425 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	
Equipment:			
Type:		#	corrective date
Comment:	Refer to Field Inspection Report doc. #696104629 and/or Location ID #302425 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Type:	Bradenhead	# 1	
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type:	Other	# 1	
Comment:	Wellhead: w/ Master & casing valves.		

Corrective Action:	Date:
--------------------	-------

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.442688,-104.498935

Comment: [Centralized Battery serves 4 Location IDs \(302425, 310494, 310631, 327512\).](#)
[Refer to Field Inspection Report doc. #696104629 and/or Location ID #302425 for Battery / Facility, Equipment info.](#)

Corrective Action:	Date:
--------------------	-------

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO			
Comment:				
Corrective Action:				Date:

Flaring:

Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 246993 Type: WELL API Number: 123-14790 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Disconnected from flowline
COGCC records indicate last production: 11/2016.
Blue TA tag posted at wellsite.
Locked-Out, Tagged-Out | LOTO.

Form 4 doc # 4402679893, TA status date: 05/01/2019. Approved.
Form 42 MIT notice on file.
Form 21-MIT doc #402032496 date: 05/02/2019. Approved.

Corrective Action:

Date: _____

BradenHead

Date of Last Brhd Test: 03/05/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On TUE 06/08/2021 at approximately 14:37 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: STATE-66N64W /36NESE Location ID: 327512 Well Name(s): State A36-9. API: 05-123-14790. Location County: Weld County, Colorado Weather: Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 4 Location IDs (302425, 310494, 310631, 327512). (Well(s): 1: Shut-In SI ; 3: Temporarily Abandoned TA).</p> <p>Refer to Field Inspection Report doc. #696104629 and/or Location ID #302425 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	06/09/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696104636	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5450256