

Inspection Photos

6/08/2021

Operator: LARAMIE ENERGY LLC # 10433

Location ID: 334550

Mesa County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 334550

Timestamp Camera



20210608

Photo 1: Photo taken from the north end of the production area, facing southeast. Photos 1-3 provide overview of the Location from southeast, south to southwest. Photo also shows bindweed establishing on the Location.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 334550



Photo 2: See comments under photo 1.



Inspection Photos

Operator Name: LARAMIE ENERGY LLC # 10433

Location ID: 334550



Photo 3: See comments under photo 1.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 334550



Photo 4: Photo taken from the southwestern area of the location, facing north. Photo shows additional reclamation and revegetation activities have been conducted. Photo also shows control measures to stabilize the soils and slopes of the Location are missing or insufficient.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 334550



Photo 5: Photo taken from the southwestern area of the location, facing northeast. Photo shows additional reclamation and revegetation activities have been conducted. Photo also shows control measures to stabilize the soils and slopes of the Location are missing or insufficient.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 334550



Photo 6: Photo taken from the southwestern area of the location, facing east. Photo shows additional reclamation and revegetation activities have been conducted. Photo also shows control measures to stabilize the soils and slopes of the Location are missing or insufficient.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 334550



Photo 7: Photo taken from the southeastern area of the location, facing north. Photo shows additional reclamation and revegetation activities have been conducted. Photo also shows control measures to stabilize the soils and slopes of the Location are missing or insufficient.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location ID: 334550



Photo 8: Photo taken from the northeastern areas of the Location, facing south. Photo shows bindweed establishment on the Location.