

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402707874

Receive Date:

Report taken by:

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

OPERATOR INFORMATION

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP	Operator No: 47120	Phone Numbers Phone: (970) 336-3500 Mobile: (970) 515-1161
Address: P O BOX 173779		
City: DENVER	State: CO Zip: 80217-3779	
Contact Person: Phillip Hamlin	Email: Phillip_Hamlin@oxy.com	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 15868 Initial Form 27 Document #: 402471008

PURPOSE INFORMATION

- ☐ Rule 913.c.(1): Pit or Cuttings Trench closure.
- ☐ Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- ☒ Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- ☐ Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- ☐ Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- ☒ Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- ☐ Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- ☐ Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- ☐ Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- ☐ Rule 913.g: Changes of Operator.
- ☐ Rule 915.b: Request to leave elevated inorganics in situ.
- ☐ Other: _____

SITE INFORMATION

Yes Multiple Facilities

Facility Type: LOCATION	Facility ID: 318080	API #: _____	County Name: WELD
Facility Name: ADDIE M. KING GAS UNIT-61N66W 4SWSW	Latitude: 40.076140	Longitude: -104.788210	
** correct Lat/Long if needed: Latitude: 40.076460		Longitude: -104.787821	
QtrQtr: SWSW	Sec: 4	Twp: 1N	Range: 66W Meridian: 6 Sensitive Area? Yes
Facility Type: SPILL OR RELEASE	Facility ID: 478864	API #: _____	County Name: WELD
Facility Name: SPILL/RELEASE POINT	Latitude: 40.076460	Longitude: -104.787821	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: SWSW	Sec: 4	Twp: 1N	Range: 66W Meridian: 6 Sensitive Area? Yes

SITE CONDITIONS

General soil type - USCS Classifications CL

Most Sensitive Adjacent Land Use Non-Crop Land

Is domestic water well within 1/4 mile? Yes

Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? Yes

Other Potential Receptors within 1/4 mile

The nearest domestic water well is located approximately 200 feet northeast of the release location. Surface water is located approximately 1,250 feet north-northeast of the release location. Multiple buildings are located within ¼ mile of the release location.

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- ☒ E&P Waste ☐ Other E&P Waste ☐ Non-E&P Waste
- ☒ Produced Water ☐ Workover Fluids
- ☒ Oil ☐ Tank Bottoms
- ☒ Condensate ☐ Pigging Waste
- ☐ Drilling Fluids ☐ Rig Wash
- ☐ Drill Cuttings ☐ Spent Filters
- ☐ Pit Bottoms
- ☐ Other (as described by EPA)

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	GROUNDWATER	See attached data	Groundwater sampling and laboratory analysis
Yes	SOILS	234' (E-W) x 128' (N-S) x 12' bgs	Excavation, soil sampling, and laboratory analysis

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

On December 7, 2020, historical impacts were discovered during abandonment activities at the King Addie M GU 1 production facility, and excavation activities were initiated. Groundwater was encountered in the excavation area at approximately 11 feet below ground surface (bgs). The COGCC issued Spill/Release Point ID 478864 for this release.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

- ☒ Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Soil samples were collected as described in a previous Form 27-Supplemental update (COGCC Document No. 402606935). Based on the data presented, impacted soils in the excavation area were remediated to be in full compliance with the COGCC Table 910-1 standards.

Proposed Groundwater Sampling

- ☒ Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Groundwater was encountered in the excavation at approximately 11 ft bgs. Groundwater samples GW01 and GW02 were collected from the excavation on December 14 and 28, 2020, respectively, and submitted for analysis of benzene, toluene, ethylbenzene, and total xylenes (BTEX). Analytical results indicated that constituent concentrations in GW01 and GW02 exceeded COGCC Table 910-1 standards. Groundwater sample GW03 was collected from the excavation on January 18, 2021, and submitted for analysis of BTEX, naphthalene, 1,2,4- and 1,3,5-trimethylbenzene (TMB), chloride, sulfate, and total dissolved solids (TDS). Analytical results indicated that constituent concentrations in GW03 were in compliance with COGCC Table 915-1 standards for organic compounds. Inorganic constituents in groundwater will be evaluated following monitoring well installation and determination of background concentrations.

Proposed Surface Water Sampling

- ☐ Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

- ☐ Additional alternative investigative actions described in attached Site Investigation Plan (summary):

The excavation groundwater sample locations are illustrated on Figure 1; groundwater analytical data is presented in Table 1. Temporary groundwater monitoring wells will be installed to fully define the extent and magnitude of the potentially remaining residual dissolved-phase groundwater impacts.

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

NA / ND

Number of soil samples collected 136

Number of soil samples exceeding 915-1 52

Was the areal and vertical extent of soil contamination delineated? Yes

Approximate areal extent (square feet) 20200

-- Highest concentration of TPH (mg/kg) 8474

-- Highest concentration of SAR 12.25

BTEX > 915-1 Yes

Vertical Extent > 915-1 (in feet) 12

Groundwater

Number of groundwater samples collected 3

Was extent of groundwater contaminated delineated? No

Depth to groundwater (below ground surface, in feet) 11'

Number of groundwater monitoring wells installed 0

Number of groundwater samples exceeding 915-1 2

-- Highest concentration of Benzene (µg/l) 426

ND Highest concentration of Toluene (µg/l)

-- Highest concentration of Ethylbenzene (µg/l) 956

-- Highest concentration of Xylene (µg/l) 16200

NA Highest concentration of Methane (mg/l)

Surface Water

0 Number of surface water samples collected

Number of surface water samples exceeding 915-1

If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

☒ Were impacts to adjacent property or offsite impacts identified?

Soil exceeding COGCC standards extended laterally beyond the lease boundary. Laboratory analytical results indicate that impacted soils in the excavation area have been remediated to be in full compliance with the COGCC Table 910-1 standards.

☐ Were background samples collected as part of this site investigation?

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)

Volume of liquid waste (barrels)

☒ Is further site investigation required?

Temporary groundwater monitoring wells will be installed to fully define the extent and magnitude of the potentially remaining residual dissolved-phase groundwater impacts. Site access and monitoring well placements are currently being considered. Subsequent to installation, the temporary groundwater monitoring wells will be sampled on a quarterly basis and submitted for laboratory analysis of of Table 915-1 constituents.

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Between December 7, 2020 and February 3, 2021, a total of approximately 7,077 cubic yards of impacted material were removed from the site. Approximately 5,950 cubic yards of impacted material were excavated and transported to the Buffalo Ridge Landfill in Keenesburg, Colorado for disposal. Approximately 1,100 cubic yards of impacted material were excavated and transported to the Kerr-McGee Land Treatment Facility in Weld County, Colorado. Approximately 27 cubic yards of impacted material were hydro-excavated and transported to the Kerr-McGee Aggregate Recycle Facility in Weld County, Colorado. Approximately 1,635 barrels of impacted groundwater were removed from the excavation via vacuum truck and transported to the Kerr-McGee Aggregate Recycle Facility in Weld County, Colorado.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Laboratory analytical results indicate that impacted soils in the excavation area have been remediated to be in full compliance with the COGCC Table 910-1 standards. Prior to backfilling, approximately 990 pounds of OxPure® activated carbon were added to the excavation to mitigate potential remaining hydrocarbon impacts to groundwater. Temporary groundwater monitoring wells will be installed to fully define the extent and magnitude of the potentially remaining residual dissolved-phase groundwater impacts. Subsequent to installation, the temporary groundwater monitoring wells will be sampled on a quarterly basis and submitted for laboratory analysis of Table 915-1 constituents. Following groundwater monitoring well installation and initiation of quarterly groundwater sampling activities, additional remediation measures may be evaluated, as necessary, to address potential remaining groundwater impacts. Estimated time to attain NFA is TBD based on the groundwater concentrations, the extent of impacted groundwater, and the efficacy of the selected remedial technologies.

Soil Remediation Summary

☐ In Situ

☒ Ex Situ

_____ Bioremediation (or enhanced bioremediation)

Yes _____ Excavate and offsite disposal

_____ Chemical oxidation

If Yes: Estimated Volume (Cubic Yards) _____ 7077

_____ Air sparge / Soil vapor extraction

Name of Licensed Disposal Facility or COGCC Facility ID # _____ 149007

_____ Natural Attenuation

_____ Excavate and onsite remediation

_____ Other _____

_____ Land Treatment

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Other _____

Groundwater Remediation Summary

No _____ Bioremediation (or enhanced bioremediation)

No _____ Chemical oxidation

No _____ Air sparge / Soil vapor extraction

Yes _____ Natural Attenuation

Yes _____ Other _____ Groundwater removal, OxPure®
activated carbon application

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Temporary groundwater monitoring wells will be installed to fully define the extent and magnitude of the potentially remaining residual dissolved-phase groundwater impacts. Site access and monitoring well placements are currently being considered. Subsequent to installation, the temporary groundwater monitoring wells will be sampled on a quarterly basis and submitted for laboratory analysis of Table 915-1 constituents. The excavation groundwater sample locations are illustrated on Figure 1, and groundwater analytical data is presented in Table 1. Subsequent to installation, a figure illustrating the locations of the surveyed temporary groundwater monitoring wells will be provided in a Form 27-Supplemental update.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Approved Reporting Schedule:

☒ Quarterly☐ Semi-Annually☐ Annually☐ Other

☐ Request Alternative Reporting Schedule:

☐ Semi-Annually☐ Annually☐ Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

Report Type:

☐ Groundwater Monitoring☐ Land Treatment Progress Report☐ O&M Report☒ Other Project status update

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? Yes

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Approximately 1,100 cubic yards of hydrocarbon-impacted soil were transported to the Kerr-McGee Land Treatment Facility in Weld County, Colorado, for recycling. Approximately 27 cubic yards of hydrocarbon-impacted soil slurry were transported to the Kerr-McGee Aggregate Recycle Facility in Weld County, Colorado, for recycling. Approximately 1,635 barrels of hydrocarbon-impacted groundwater were transported to the Kerr-McGee Aggregate Recycle Facility in Weld County, Colorado, for recycling.

Volume of E&P Waste (solid) in cubic yards 7077

E&P waste (solid) description Hydrocarbon-impacted soil

COGCC Disposal Facility ID #, if applicable: 149007

Non-COGCC Disposal Facility: Buffalo Ridge Landfill - Keenesburg, Colorado

Volume of E&P Waste (liquid) in barrels 1635

E&P waste (liquid) description Hydrocarbon-impacted groundwater

COGCC Disposal Facility ID #, if applicable: 434766

Non-COGCC Disposal Facility:

REMEDIATION COMPLETION REPORT

REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No

If YES:

☐ Compliant with Rule 913.h.(1).

☐ Compliant with Rule 913.h.(2).

☐ Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards? No

Does the previous reply indicate consideration of background concentrations?

Does Groundwater meet Table 915-1 standards? No

Is additional groundwater monitoring to be conducted? Yes

Operator shall comply with the COGCC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

The site has been restored to its pre-release grade. Kerr-McGee will conduct reclamation activities in accordance with COGCC 1000 Series Rules.

Is the described reclamation complete? No _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim

☐ Final

Did the Surface Owner provide the seed mix? _____

If YES, does the seed mix comply with local soil conservation district recommendations? _____

Did the local soil conservation district provide the seed mix? _____

SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. _____

Proposed date of completion of Reclamation. _____

IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

PRIOR DATES

Date of Surface Owner notification/consultation, if required. 12/14/2020

Actual Spill or Release date, or date of discovery. 12/07/2020

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 12/07/2020

Proposed site investigation commencement. 12/07/2020

Proposed completion of site investigation. _____

REMEDIAL ACTION DATES

Proposed start date of Remediation. 12/07/2020

Proposed date of completion of Remediation. _____

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

☐ Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

OPERATOR COMMENT

Form 27-Supplemental Updates will be submitted to the COGCC on a quarterly basis until the extent of groundwater impacts has been fully delineated. The Project Implementation Summary is provided as Attachment A.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: ` Phillip Hamlin

Title: Senior Environmental Rep

Submit Date: `

Email: Phillip_Hamlin@oxy.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____

Date: _____

Remediation Project Number: 15868

COA Type**Description**

--	--

Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num**Name**

402707930	GROUND WATER SAMPLE LOCATION
402707940	ANALYTICAL RESULTS
402714952	IMPLEMENTATION SCHEDULE

Total Attach: 3 Files

General Comments**User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)