

Inspection Photos
Location Name: UPRR 43 Pan AM #8
Location ID: 318429



Photo 1 loc pic



Photo 2 loc pic. Flow line valves not bullplugged and LOTO

Inspection Photos
Location Name: UPRR 43 Pan AM #8
Location ID: 318429



Photo 3 meter panel (WEEDS)



Photo 4 loc pic