

Inspection Photos  
Location Name: Carl R Deepe C 2  
Location ID: 318388



Photo 1 WH/sign

Photo 2 WH

**Inspection Photos**  
**Location Name: Carl R Deepe C 2**  
**Location ID: 318388**



**Photo 3 Tall weeds growing around ancillary equipment**

**Photo 4 Tall weeds growing along access road**

**Inspection Photos**  
**Location Name: Carl R Deepe C 2**  
**Location ID: 318388**



**Photo 5 Pump Jack, Tall weeds growing around location ROW**

**Photo 4 Pump Jack Tall weeds growing around location**