

**Inspection Photos**  
**Location Name: Spurling 35N-34HZ**  
**Location ID: 436137**



**Photo 1 WH/sign**



**Photo 2 WH/sign**

**Inspection Photos**  
**Location Name: Spurling 35N-34HZ**  
**Location ID: 436137**



**Photo 3 WH/sign**




**Photo 4 WH/sign**

**Inspection Photos**  
**Location Name: Spurling 35N-34HZ**  
**Location ID: 436137**



**Photo 5 WH/sign**



**Photo 6 WH/sign**



**Inspection Photos**  
**Location Name: Spurling 35N-34HZ**  
**Location ID: 436137**



**Photo 7 TB signs**



**Photo 8 TB**

**Inspection Photos**  
**Location Name: Spurling 35N-34HZ**  
**Location ID: 436137**



**Photo 9 LACT house**



**Photo 10 FWKOs**

**Inspection Photos**  
**Location Name: Spurling 35N-34HZ**  
**Location ID: 436137**



**Photo 11 VRU**



**Photo 12 Compressor**



**Inspection Photos**  
**Location Name: Spurling 35N-34HZ**  
**Location ID: 436137**



**Photo 13 Horizontal Heated Separators**



**Photo 14 ECD**

# Inspection Photos

Location Name: Spurling 35N-34HZ  
Location ID: 436137




Photo 15 Gas Meter Run

Photo 16 Cards in meter house indicate current calibration



**Inspection Photos**  
**Location Name: Spurling 35N-34HZ**  
**Location ID: 436137**



**Photo 17 VRT**