

**Inspection Photos**  
**Location Name: Jillson A 1**  
**API 05-123-08777; Spill ID 478617**



**Photo 1 Well Sign**



**Photo 2 Excavation around wellhead and casing**





**Inspection Photos**  
**Location Name: Jillson A 1**  
**API 05-123-08777; Spill ID 478617**



**Photo 3 Well casing leak**



**Photo 4 Well Casing Leak**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Inspection Photos**  
**Location Name: Jillson A 1**  
**API 05-123-08777; Spill ID 478617**



**Photo 5 Leak at piping header at tank battery**



**Photo 6 Produced Water Tank**

