

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Bird Protectors	# 4		corrective date
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 3		

Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	110 Bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shared with condensate tank.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		40.184970,-104.852950
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Wells Served By Facilities Above

AirsID

API Number
123-07324
123-19760
123-19928
123-19505

API Number	AirsID
------------	--------

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 239537 Type: WELL API Number: 123-07324 Status: PR Insp. Status: PR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI at wellhead.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 03/12/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: -- Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: Plumbed to surface.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Routine wellhead and battery inspection.	carlilec	06/11/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690007701	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5453340