

Inspection Photos

Loc#428533

Operator: GRMR

Insp#: 692403447

Insp Date: 5/27/2021



Photo#1:
View over Location to Northeast.

May 27, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: GRMR North Castor Gulch Loc#428533



Photo#2:
View to South over location vegetation.



Photo#3:
View to East over location vegetation.

May 27, 2021



Photo#4:
View Southeast along road leading into Location.



Photo#5:
Turnaround at termination of road at Location.

May 27, 2021



Photo#6:
Steep Cut on portions of road.

Photo#7:
Ditch along Fill side of road.

May 27, 2021