

Inspection Photos

API#081-05171

Loc#312760

Operator: GRMR

Insp#: 692403451

Insp Date: 5/27/2021



Photo#1:
View over Location to West.

May 27, 2021



Photo#2:
PA Marker and remediation project.



Photo#3:
Weeds on edge of Location.

May 27, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: GRMR PA Durham API#081-05171



Photo#4:
View over site to Southeast and entry.

May 27, 2021