

**Inspection Photos**  
**Operator: Crescent Point**  
**API: 113-06220**  
**Date: 6/8/2021**



Photo 1. View of access road facing westward.



Photo 2. View of stabilization measures installed at culvert outlet along the access road in response to 2020 corrective actions.



Photos 3. View of culvert inlet along the access road.