

Inspection Photos

Operator: Paradox Upstream
API: 113-06096
Date: 6/8/2021



Photo 1. View the project area from the northwestern corner facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing with western wheatgrass, winterfat, and needleandthread grass.



Photos 3/4. View of bare and eroding soils in the northeastern corner of the project area. Stormwater and erosion controls need to be installed to stabilize erosion here.



Photos 5. View of reference area comprised of sagebrush shrubland with an understory of James galleta, needleandthread grass, and sego lily.