

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Gardner Federal /28-1 (PC-28)

Location ID: 311692



**Photo #4071 from entrance to location.**



**Photo #4072 No battery sign located at the tank battery.**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC Gardner Federal /28-1 (PC-28)

Location ID: 311692



**Photo #4073 Multiple flow line heating insulation open ended and not capped.**



**Photo #4074 Multiple flow line heating insulation open ended and not capped.**