

Inspection Photos

API: 061-06713

Operator: THOMAS L SPRING LLC

Inspection Date: 6/9/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06713 | Date: 6/9/2021

Inspection Photos



Photo 1. Facing north along the two track access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06713 | Date: 6/9/2021

Inspection Photos



Photo 2. Facing north toward the location. All equipment has been removed. There are areas with no vegetation growth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06713 | Date: 6/9/2021

Inspection Photos



Photo 3. Facing west toward the location. All equipment has been removed. There are areas with no vegetation growth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06713 | Date: 6/9/2021