

Inspection Photos

ID: 412295

Operator: RENCO GAS PIPELINE INC

Inspection Date: 6/9/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast at the location. Tank has not been removed and soils have no vegetation growth indicating a potential spill area.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

412295 | Date: 6/9/2021

Inspection Photos



Photo 2. Abandoned pipe risers have not been removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

412295 | Date: 6/9/2021

Inspection Photos



Photo 3. Abandoned engine compressor has not been removed. Previous corrective action was not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

412295 | Date: 6/9/2021