

Inspection Photos

API: 061-06480

Operator: MURFIN DRILLING COMPANY INC

Inspection Date: 6/9/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06480 | Date: 6/9/2021

Inspection Photos



Photo 1. Facing northwest toward the location. Areas of the location remain bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06480 | Date: 6/9/2021

Inspection Photos



Photo 2. Facing north at the location. Areas of the location remain bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06480 | Date: 6/9/2021

Inspection Photos



Photo 3. Facing northeast at the location. Areas of the location remain bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06480 | Date: 6/9/2021