

Inspection Photos
Operator: Paradox Upstream
API: 113-06144
Date: 6/8/2021



Photo 1. View the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing with James galleta, western wheatgrass, crested wheatgrass, and rubber rabbitbrush.



Photos 3. View of reference area comprised of sagebrush shrubland with an understory of James galleta, needleandthread grass, and sego lily.