

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402630066

Receive Date:

04/05/2021

Report taken by:

Steven Arauza

Site Investigation and Remediation Workplan (Initial Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

OPERATOR INFORMATION

Name of Operator: CAERUS PICEANCE LLC	Operator No: 10456	Phone Numbers
Address: 1001 17TH STREET #1600		Phone: (970) 285.2739
City: DENVER State: CO Zip: 80202		Mobile: (970) 987.4650
Contact Person: Brett Middleton	Email: bmiddleton@caerusoilandgas.com	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 18506

Initial Form 27 Document #: 402630066

PURPOSE INFORMATION

- | | |
|--|--|
| <input type="checkbox"/> 901.e. Sensitive Area Determination | <input type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water |
| <input type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure | <input type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b. |
| <input checked="" type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation | <input type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project |
| <input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste | <input type="checkbox"/> Rule 906.c.: Director request |
| <input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure | <input type="checkbox"/> Other _____ |

SITE INFORMATION

N Multiple Facilities (in accordance with Rule 909.c.)

Facility Type: WELL	Facility ID: _____	API #: 045-14507	County Name: GARFIELD
Facility Name: 696-18C 14	Latitude: 39.519800	Longitude: -108.156490	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: NWSW	Sec: 18	Twp: 6S	Range: 96W Meridian: 6 Sensitive Area? Yes

SITE CONDITIONS

General soil type - USCS Classifications GC

Most Sensitive Adjacent Land Use Rangeland

Is domestic water well within 1/4 mile? No

Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

Unnamed spring located 0.16 miles to the northeast

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- ☒ E&P Waste ☐ Other E&P Waste ☐ Non-E&P Waste
- ☐ Produced Water ☐ Workover Fluids
- ☐ Oil ☐ Tank Bottoms
- ☐ Condensate ☐ Pigging Waste
- ☒ Drilling Fluids ☐ Rig Wash
- ☐ Drill Cuttings ☐ Spent Filters
- ☐ Pit Bottoms
- ☐ Other (as described by EPA)

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	SOILS	75' X 75'	Visual

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

From Historic Form 19 (Doc 1630706):

The well began to flow up through the rotary and the blind rams were closed (no drill pipe in the well). A significant leak of water based mud and air (with limited gas) was subsequently observed within the wellhead area from the wellhead hold-down pins and packing glands, which had been loosened to release the wear bushing and in preparation to lock in the false bowl.

100 bbls mud/water spilled and 100 bbls mud/water recovered

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

☒ Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Please see the attached Spill Investigation Site Diagram for proposed spill investigation points. These points were selected to characterize the approximate spill area from the reported surface spill. Caerus will investigate each identified surface spill location between zero (0) and six (6) inches below ground surface. Each spill investigation area will be field-screened with visual and olfactory observations and a photo-ionization detector (PID) to identify potentially impacted soil. Investigated soil will also be photographed to document presence/absence of soil staining. If no impacts are identified during the investigation, Caerus will document these findings without sample collection on a Supplemental Form 27. Continued in Operator Comments

Proposed Groundwater Sampling

☐ Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

If groundwater is encountered at any of the proposed sampling locations Caerus will attempt to collect a representative groundwater sample for laboratory analysis with findings reported in a supplemental Form 27.

Proposed Surface Water Sampling

☐ Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

☒ Additional alternative investigative actions described in attached Site Investigation Plan (summary):

Caerus requests to utilize COGCC Rule 915.f. for the project to be completed prior to January 15, 2022.

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 0
Number of soil samples exceeding 910-1
Was the areal and vertical extent of soil contamination delineated?
Approximate areal extent (square feet)

NA / ND

 Highest concentration of TPH (mg/kg)
 Highest concentration of SAR
 BTEX > 910-1
 Vertical Extent > 910-1 (in feet)

Groundwater

Number of groundwater samples collected 0
Was extent of groundwater contaminated delineated? No
Depth to groundwater (below ground surface, in feet)
Number of groundwater monitoring wells installed
Number of groundwater samples exceeding 910-1

 Highest concentration of Benzene (µg/l)
 Highest concentration of Toluene (µg/l)
 Highest concentration of Ethylbenzene (µg/l)
 Highest concentration of Xylene (µg/l)
 Highest concentration of Methane (mg/l)

Surface Water

0 Number of surface water samples collected
 Number of surface water samples exceeding 910-1
If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

☐ Were impacts to adjacent property or offsite impacts identified?

☒ Were background samples collected as part of this site investigation?

Based on internal document review and proposed spill investigation results, background soil samples may be collected at the location. Background data will be presented in a supplemental Form 27

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) Volume of liquid waste (barrels)

☒ Is further site investigation required?

This Remediation Workplan includes a proposed spill investigation plan. With approval and weather permitting, investigation activities will be conducted, and results will be reported in a supplemental Form 27.

REMEDIAL ACTION PLAN

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

With approval of Rule 915.f allowing clearance under Table 910-1, if investigation activities identify concentrations of analytes exceeding COGCC Table 910-1 Concentration Levels, additional site investigation activities and remedial actions will be proposed in a supplemental Form 27

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

With approval of Rule 915.f allowing clearance under Table 910-1, if investigation activities identify concentrations of analytes exceeding COGCC Table 910-1 Concentration Levels, additional site investigation activities and remedial actions will be proposed in a supplemental Form 27

Soil Remediation Summary

☐ In Situ

- ☐ Bioremediation (or enhanced bioremediation)
- ☐ Chemical oxidation
- ☐ Air sparge / Soil vapor extraction
- ☐ Natural Attenuation
- ☐ Other _____

☐ Ex Situ

- ☐ Excavate and offsite disposal
- ☐ If Yes: Estimated Volume (Cubic Yards) _____
- ☐ Name of Licensed Disposal Facility or COGCC Facility ID # _____
- ☐ Excavate and onsite remediation
- ☐ Land Treatment
- ☐ Bioremediation (or enhanced bioremediation)
- ☐ Chemical oxidation
- ☐ Other _____

Groundwater Remediation Summary

- ☐ Bioremediation (or enhanced bioremediation)
- ☐ Chemical oxidation
- ☐ Air sparge / Soil vapor extraction
- ☐ Natural Attenuation
- ☐ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

REMEDATION PROGRESS UPDATE

PERIODIC REPORTING

Frequency: ☐ Quarterly ☐ Semi-Annually ☐ Annually ☒ Other See site investigation plan.

Report Type: ☐ Groundwater Monitoring ☐ Land Treatment Progress Report ☐ O&M Report

☒ Other REM Progress report

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? _____

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards _____

E&P waste (solid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

Volume of E&P Waste (liquid) in barrels _____

E&P waste (liquid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Any disturbance will be returned to the pre-existing conditions for continued activity. When the site is decommissioned at a later date, it will be reclaimed in accordance with 1000 Series regulations.

Is the described reclamation complete? ☐ No _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim?

☐ Final?

Did the Surface Owner approve the seed mix? _____

If NO, does the seed mix comply with local soil conservation district recommendations? _____

IMPLEMENTATION SCHEDULE

PRIOR DATES

Date of Surface Owner notification/consultation, if required. _____

Actual Spill or Release date, if known. 02/16/2008

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 02/16/2008

Date of commencement of Site Investigation. _____

Date of completion of Site Investigation. _____

REMEDIAL ACTION DATES

Date of commencement of Remediation. _____

Date of completion of Remediation. _____

SITE RECLAMATION DATES

Date of commencement of Reclamation. _____

Date of completion of Reclamation. _____

OPERATOR COMMENT

Continuation from Proposed Soil Sampling Plan on Site Investigation Plan tab: Under COGCC Rule 915.f, Caerus requests the Director's permission to comply with the version of Table 910-1 that was previously in effect if Remediation is completed by January 15, 2022. If impacts are identified during investigation activities, Caerus will collect samples from each impacted soil interval to be analyzed for COGCC Table 910-1 analytes. The number of spill investigation points may vary based on onsite assessment.

With Form 27 approval and remediation project number assignment, Caerus requests closure of COGCC Spill Document Number 1630706 as subsequent site investigation and remediation work will proceed under the assigned remediation project number.

As part of the historic spill project review and document preparation, Caerus will be implementing a phased approach to prioritize sampling and investigation.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: ` Reed Johnson

Title: Sr. Project Geologist

Submit Date: ` 04/05/2021

Email: rjohnson@entradainc.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Steven Arauza

Date: 06/14/2021

Remediation Project Number: 18506

Condition of Approval**COA Type****Description**

	Based on the information provided, the Operator's request to proceed under Table 910-1 is conditionally approved pursuant to Rule 915.f. Per Rule 915.f, if the remediation is not completed by January 15, 2022, then the Operator will comply with the current version of Table 915-1.
	Operator shall collect sample(s) from comparable, nearby non-impacted native soil for purposes of establishing background soil conditions including pH, electrical conductivity (EC) and sodium adsorption ratio (SAR), per Rule 915.e.(2).D.
	Per Rule 913.b.(2), the Operator will conduct sampling and analysis of soil, and groundwater--if encountered, to determine the horizontal and vertical extent of any contamination in excess of the cleanup concentrations in Table 910-1 for soil and groundwater. The Operator shall analyze samples for the complete Table 910-1 list. If groundwater is encountered during remediation activities, the Operator shall comply with Table 915-1 using the Protection of Groundwater Soil Screening Level Concentrations.
	Operator shall collect an appropriate number of representative soil samples to delineate the horizontal and vertical extents of contamination, per Rule 915.e.(2).B.
4 COAs	

Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num**Name**

402630066	FORM 27-INITIAL-SUBMITTED
402630338	OTHER
402642814	MAP

Total Attach: 3 Files

General Comments**User Group****Comment****Comment Date**

Environmental	COGCC GISOnline Map Viewer topographic map indicates the presence of Springs approximately 870' NE of the spill investigation area.	06/14/2021
---------------	---	------------

Total: 1 comment(s)