

Inspection Photos

6/10/2021

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335171

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 335171



Photo 1: Photo taken from the cut slopes on the north end of the Location. Photo shows control measures to protect and stabilize the cut slopes of the Location remain missing or insufficient; corrective action not addressed



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 335171



Photo 2: Photo taken from the cut slopes on the north end of the Location. Photo shows control measures to protect and stabilize the cut slopes of the Location remain missing or insufficient; corrective action not addressed



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 335171



Photo 3: Photo taken from the cut slopes on the north end of the Location. Photo shows control measures to protect and stabilize the cut slopes of the Location remain missing or insufficient; corrective action not addressed



Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335171



Photo 4: Photo taken from the cut slopes on the north end of the Location. Photo shows control measures to protect and stabilize the cut slopes of the Location remain missing or insufficient; corrective action not addressed



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 335171



Photo 5: Photo taken from the cut slopes on the north end of the Location. Photo shows control measures to protect and stabilize the cut slopes of the Location remain missing or insufficient; corrective action not addressed

