

# Inspection Photos

API: 017-07743

Operator: MULL DRILLING COMPANY

Inspection Date: 6/9/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07743 | Date: 6/9/2021

## Inspection Photos



**Photo 1.** Facing west at the location. No crop was planted at the location this year to evaluate crop growth. All equipment has been removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07743 | Date: 6/9/2021