

North Platte 21-24 Production Facility

Location ID 470676

Remediation # 17894

Decommissioning Assessment


May 2021




EAGLE
ENVIRONMENTAL
CONSULTING, INC.
8000 W 44th Ave, Wheat Ridge, CO 80033
Ph: 303-433-0479 • F: 303-325-5449



Tank Battery Decommissioning Assessment / Sampling – 05/27/21



Looking north
Produced water vault excavation – vault removed prior to arrival
No petroleum hydrocarbon staining or odor observed
Samples collected:
WV-SS-01@3' – 1.3 ppm-v
WV-SS-04@3' – 4.6 ppm-v
WV-FS-03@6.5' – 5.2 ppm-v



Looking south
Produced water vault excavation – vault removed prior to arrival
No petroleum hydrocarbon staining or odor observed
Samples collected:
WV-SS-02@3' – 8.1 ppm-v
WV-SS-03@3' – 8.5 ppm-v
WV-FS-03@6.5' – 5.2 ppm-v

Tank Battery Decommissioning Assessment / Sampling – 05/27/21



Looking east-northeast
Separator containment area – separators removed prior to arrival
No petroleum hydrocarbon staining or odor observed
Samples collected:
TB-SS-04@0-0.25' – 6.1 ppm-v
TB-SS-05@0-0.25' – 5.5 ppm-v
TB-SS-06@0-0.25' – 15.6 ppm-v

Looking north-northwest
Former ECD locations – removed prior to arrival
No petroleum hydrocarbon staining or odor observed
Samples collected:
TB-SS-07@0-0.25' – 2.3 ppm-v

Tank Battery Decommissioning Assessment / Sampling – 05/27/21



Looking west-southwest

Production tank connection points

Tanks appeared in good condition

No petroleum hydrocarbon staining or odor observed

Soil samples collected:

TB-SS-01@0-0.25' – 9.3 ppm-v

TB-SS-02@0-0.25' – 7.1 ppm-v

TB-SS-03@0-0.25' – 7.8 ppm-v