

Inspection Photos

API: 017-07561

Operator: PRONGHORN OPERATING LLC

Inspection Date: 6/9/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07561 | Date: 6/9/2021

Inspection Photos



Photo 1. Facing south at the location. The crop has not uniformly re-established at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07561 | Date: 6/9/2021

Inspection Photos



Photo 2. Facing west at the location. The crop has not uniformly re-established at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07561 | Date: 6/9/2021

Inspection Photos



Photo 3. There are undesirable weeds and a wood beam that remains at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07561 | Date: 6/9/2021

Inspection Photos



Photo 4. Facing east toward the surrounding undisturbed cropfield.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07561 | Date: 6/9/2021