

# *Inspection Photos*

*API#057-06462*

*Operator: Farleigh Oil*

*Inspection Number: 692403519*

*Inspection Date: 6/10/21*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:

Overview of Location to Northwest; in foreground is portion of access road to remain.

November 6, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Farleigh Oil PA Silver Spur API#057-06462





Photo#2:  
Overview of area of concern to Northeast.

November 6, 2019





Photo#3:

Overview of Location to Southwest; arrow indicating entry and access road to remain.

November 6, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Farleigh Oil PA Silver Spur API#057-06462