

Final Reclamation Inspection

June 3, 2021

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 336181

Inspection Document #: 697503006

Weld County, CO

NESW Section 35 T2N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: LANSONS FARM/NAV/-62N68W /35NESW

Location ID: 336181



Photo 1. Photo taken from the northern location, facing West. Photo illustrates the location meets final reclamation rules.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697503006

Inspection Photos

Location Name: LANSONS FARM/NAV/-62N68W /35NESW

Location ID: 336181



Photo 2. Photo taken from the western location, facing Southwest. See comments under Photo 1.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697503006