

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/03/2021

Submitted Date:

06/14/2021

Document Number:

697503006

**FIELD INSPECTION FORM**Loc ID 336181 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                         | Comment         |
|--------------|-------|-------------------------------|-----------------|
| ,            |       | COGCCinspections@anadarko.com | All inspections |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name       | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 247443      | WELL | PA     | 05/25/2018  | OW         | 123-15240 | LANSONS FARM/NAV/ 3 | RI          |
| 299464      | WELL | PA     | 05/24/2018  | OW         | 123-29379 | NELSON 33-35        | RI          |
| 299465      | WELL | PA     | 05/23/2018  | OW         | 123-29380 | NELSON 13-35        | RI          |
| 299466      | WELL | PA     | 05/24/2018  | OW         | 123-29381 | NELSON 12-35        | RI          |
| 299470      | WELL | PA     | 05/24/2018  | OW         | 123-29383 | NELSON 23-35        | RI          |
| 299471      | WELL | PA     | 05/24/2018  | OW         | 123-29384 | NELSON 11-35        | RI          |
| 299472      | WELL | PA     | 05/23/2018  | OG         | 123-29385 | NELSON 14-35        | RI          |

**General Comment:**

This is a Final Reclamation Inspection at a plugged and abandoned multi-well location. The last well (123-15240) plugged and abandoned was on 5/25/2018.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

|                    |   |       |                 |
|--------------------|---|-------|-----------------|
| Type:              | #   |       | corrective date |
| Comment:           | No visual evidence of oil and gas equipment at the location. Refer to the attached inspection photos. |       |                 |
| Corrective Action: |   | Date: |                 |

**Venting:**

|                    |  |       |
|--------------------|--|-------|
| Yes/No             |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities |               |       |             |             |                  |         |           |               |           |
|----------------------|---------------|-------|-------------|-------------|------------------|---------|-----------|---------------|-----------|
| Facility ID:         | <u>247443</u> | Type: | <u>WELL</u> | API Number: | <u>123-15240</u> | Status: | <u>PA</u> | Insp. Status: | <u>RI</u> |
|                      |               |       |             |             |                  |         |           |               |           |
| Facility ID:         | <u>299464</u> | Type: | <u>WELL</u> | API Number: | <u>123-29379</u> | Status: | <u>PA</u> | Insp. Status: | <u>RI</u> |
|                      |               |       |             |             |                  |         |           |               |           |
| Facility ID:         | <u>299465</u> | Type: | <u>WELL</u> | API Number: | <u>123-29380</u> | Status: | <u>PA</u> | Insp. Status: | <u>RI</u> |
|                      |               |       |             |             |                  |         |           |               |           |
| Facility ID:         | <u>299466</u> | Type: | <u>WELL</u> | API Number: | <u>123-29381</u> | Status: | <u>PA</u> | Insp. Status: | <u>RI</u> |
|                      |               |       |             |             |                  |         |           |               |           |
| Facility ID:         | <u>299470</u> | Type: | <u>WELL</u> | API Number: | <u>123-29383</u> | Status: | <u>PA</u> | Insp. Status: | <u>RI</u> |
|                      |               |       |             |             |                  |         |           |               |           |
| Facility ID:         | <u>299471</u> | Type: | <u>WELL</u> | API Number: | <u>123-29384</u> | Status: | <u>PA</u> | Insp. Status: | <u>RI</u> |
|                      |               |       |             |             |                  |         |           |               |           |
| Facility ID:         | <u>299472</u> | Type: | <u>WELL</u> | API Number: | <u>123-29385</u> | Status: | <u>PA</u> | Insp. Status: | <u>RI</u> |

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

**Overall Interim Reclamation****Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged Pass Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed Pass No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed Pass Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage Pass

Weeds present Pass Subsidence Pass

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: The location meets final reclamation regulations and standards. Unable to find evidence of oil and gas activities and/or disturbances. Location appears reflective of reference crop areas.

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation Pass Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: [At the time of this inspection, no stormwater erosion issues were observed.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 697503007    | Inspection Photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5454729">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5454729</a> |