

# Inspection Photos

API: 017-07804

Operator: ANGUS NATURAL RESOURCES LLC

Inspection Date: 6/9/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07804 | Date: 6/9/2021

## Inspection Photos



**Photo 1.** Facing north toward the location . Desirable vegetation has not re-established to 80% cover at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07804 | Date: 6/9/2021

## Inspection Photos



**Photo 2.** Facing north at the location. Vegetation growth in this area is predominately undesirable weeds (Kochia sp., Field bindweed).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07804 | Date: 6/9/2021

## Inspection Photos



**Photo 3.** View of groundcover shows mostly undesirable weeds (Field bindweed).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07804 | Date: 6/9/2021

## Inspection Photos



**Photo 4.** Facing northwest at the location. Vegetation growth in this area is predominately undesirable weeds (Kochia).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07804 | Date: 6/9/2021

## Inspection Photos



**Photo 5.** View of groundcover shows mostly undesirable weeds (*Kochia* sp.).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07804 | Date: 6/9/2021

## Inspection Photos



**Photo 6.** Facing south toward the adjacent undisturbed surrounding reference area which consists of Blue grama, Sand dropseed, Side oats grama, among other desirable species.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07804 | Date: 6/9/2021