

# Inspection Photos

Operator: Paradox Upstream  
API: 113-06143  
Date: 6/9/2021



Photo 1. View the project area from the northeastern corner facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing with rubber rabbitbrush, fourwing saltbush, squirreltail, western wheatgrass, and Indian ricegrass.





Photo 3. View of the eastern project area from the northeastern corner facing southward.





Photo 4. View of reference area comprised of pinyon and juniper woodland with an understory of mountain mahogany, *Tetrandeum* sp., ephedra, yucca, and Indian ricegrass.