

Inspection Photos

Operator: Paradox Upstream
API: 113-06145
Date: 6/9/2021



Photo 1. View the project area from the northwestern corner facing westward. Revegetation is progressing with fourwingsaltbush, squirreltail, and Indian ricegrass.



Photo 2. View of the western project area from the northwestern corner facing southward.



Photo 3. View of the southern project area eastward.



Photo 4. View of reference area comprised of pinyon and juniper woodland with an understory of mountain mahogany, *Tetrandeum* sp., ephedra, yucca, and Indian ricegrass.