

Inspection Photos
Operator: Huntington Energy
API: 113-06199
Date: 6/9/2021



Photo 1. View the project area from the well pad entrance facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing with western wheatgrass and squirreltail.



Photo 3. View of the eastern project area from the northeastern corner facing southward.



Photo 4. View of reference area comprised of open sagebrush shrubland with black sagebrush, winterfat, squirreltail, and snakeweed.