

# Inspection Photos

API: 017-07809

Operator: MCCOY PETROLEUM CORPORATION

Inspection Date: 6/9/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07809 | Date: 6/9/2021

Inspection Photos



**Photo 1.** Facing north toward the former access road which has been reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07809 | Date: 6/9/2021

## Inspection Photos



**Photo 2.** Facing north toward the location which has been recontoured and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07809 | Date: 6/9/2021

## Inspection Photos



**Photo 3.** View of groundcover shows Alfalfa and wheat and also some perennial grass species.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07809 | Date: 6/9/2021

## Inspection Photos



**Photo 4.** Facing north at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07809 | Date: 6/9/2021

## Inspection Photos



**Photo 5.** Facing east toward the surrounding undisturbed reference area which consists of Blue grama, Side oats grama, Sand drop seed among other species.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07809 | Date: 6/9/2021