

# Inspection Photos

API: 061-06366

Operator: SAMSON OIL COMPANY

Inspection Date: 6/9/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06366 | Date: 6/9/2021

## Inspection Photos



**Photo 1.** Facing south toward the location. The reclaimed area is fenced.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06366 | Date: 6/9/2021

## Inspection Photos



**Photo 2.** The vegetation appears to be progressing within the fenced area. This area has not yet reached 80% cover of reference levels.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06366 | Date: 6/9/2021

## Inspection Photos



**Photo 3.** View of groundcover.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06366 | Date: 6/9/2021