


Inspection Photos  
Location Name: Buchner 2-2H  
Location ID: 431634



Colorado Oil and Gas Conservation Commission  
40.60369, -104.06671, 4875.5ft, 111°  
06/10/2021 13:45:20



Colorado Oil and Gas Conservation Commission  
40.60368, -104.06666, 4880.7ft, 346°  
06/10/2021 13:45:28

Photo 1 – Wellhead

Photo 2 – Wellhead Sign

**Inspection Photos**  
**Location Name: Buchner 2-2H**  
**Location ID: 431634**



**Photo 3 – Flare and ECD**

**Photo 4 – Tank Labels Missing**

**Inspection Photos**  
**Location Name: Buchner 2-2H**  
**Location ID: 431634**



**Photo 5 – Stained Soil at Gear Box**

**Photo 6 – Gear Box leaking**

**Inspection Photos**  
**Location Name: Buchner 2-2H**  
**Location ID: 431634**



**Photo 7 – Stained Soil at Gear Box**

**Photo 8 – Gear Box Leaking**

**Inspection Photos**  
**Location Name: Buchner 2-2H**  
**Location ID: 431634**



**Photo 9 – Stained Soil at Gas Engine**

**Photo 10 – Heater Treater**

Inspection Photos  
Location Name: Buchner 2-2H  
Location ID: 431634



**Photo 11 – Tank Battery**