

Inspection Photos

Loc#438248

Operator: SWN

Insp#: 692403494

Insp Date: 6/8/2021



Photo#1:
View of Location from entry to Northwest.

June 6, 2021



Photo#2:

Overview of Location from Southwest corner to Northeast.

June 6, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: SWN Diamond T Sheep Loc#438248



Photo#3:
Affected Weeds(Scotch thistle) on Fill slope



Photo#4:
Affected Weeds(Scotch thistle) on Pad.

June 6, 2021



Photo#5:
Senesced weeds on berms.

Photo#6:
Senesced weeds on Pad.

June 6, 2021



Photo#7:
Senesced weeds on berrms.



Photo#8:
Cheat grass on fill slope and berms.

June 6, 2021



Photo#9:
Undesirable vegetation on Fill slope.



Photo#10:
Cheat grass on fill slope and berms.

June 6, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: SWN Diamond T Sheep Loc#438248



Photo#11:
Senesced weeds blown into equipment



Photo#12:
Senesced weeds on berms.

June 6, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: SWN Diamond T Sheep Loc#438248



Photo#13:
Unused equipment on Location.

June 6, 2021



Photo#14:
2015 COGCC Maps Aerial image of Location.



Photo#15:
2019 COGCC Maps Aerial image of Location

June 6, 2021