

Inspection Photos
Operator: Paradox Upstream
API: 113-06091
Date: 6/9/2021





Photo 1. View the project area from the northern project area facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing with western wheatgrass, rubber rabbitbrush, fourwing saltbush, and squirreltail.



Photo 3. View of the northern project area from the northwestern corner facing eastward.



Photos 4-6. View of tamarisk (left; approx. 7 individuals) and Russian knapweeds (right; approx. 300 individuals) observed along the access road.



Photo7. View of reference area comprised of pinyon and juniper woodland mixed with sagebrush, James galleta, snakeweed, and goldenasters.