

Inspection Photos

Operator: Paradox Upstream
API: 113-06092
Date: 6/9/2021



Photo 1. View the project area from the eastern edge facing center.



Photo 2. View of the northern project area from the northeastern corner facing eastward. Revegetation remains sparse with significant portions dominated by kochia, seedlings, other portions are progressing with western wheatgrass and squirreltail.



Photo 3. View of fenced area in the southern project area with little desirable vegetative cover.



Photo 4. View of reference area comprised of pinyon and juniper woodland mixed with sagebrush, James galleta, snakeweed, and goldenasters.