

Inspection Photos
Operator: Paradox Upstream
API: 113-06181
Date: 6/9/2021



Photo 1. View the project area from the northeastern edge facing center.




Photo 2. View the northeastern project area facing westward. Revegetation within fenced area is sparse, and largely comprised of weedy kochia and cheatgrass.



Photo 3. View of the northwestern project area from the northern edge facing westward. Revegetation is progressing within this portion of the project area with western wheatgrass, fourwing saltbush, and James galleta.



Photo 4. View of the western project area from the northwestern corner facing southward.



Photo 5. View of reference area comprised of pinyon and juniper woodland mixed with sagebrush, James galleta, snakeweed, and goldenasters.