

Inspection Photos

Operator: Paradox Upstream
API: 113-06159
Date: 6/9/2021



Photo 1. View the project area from the northeastern corner facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing with western wheatgrass, winterfat, rubber rabbitbrush, and sagebrush.



Photo 3. View of reference area comprised of pinyon and juniper woodland mixed with sagebrush, James galleta, snakeweed, and goldenasters.