

Inspection Photos

API#045-06290

Operator: Maralex

Insp #: 692403486

Insp Date: 6/3/2021





Photo#1:
Overview of Location from access road entry to West.

June 3, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Maralex PA Rifle-Walton API#045-06290



Photo#2:

View of Location from North side of site to South, showing gravel and compacted surfaces.

June 3, 2021




Photo#3:
Cut slope on West side of site.



Photo#4:
Equipment on site; Surface Owner?

June 3, 2021



Photo#5:
Noxious weeds, Houndstongue, Thistle & White top
on site.

Photo#6:
Noxious weeds, Houndstongue, Thistle & White top
on site.

June 3, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Maralex PA Rifle-Walton API#045-06290