

Inspection Photos

API#107-06042

Operator: Booco's

Insp#: 692403497

Insp Date: 6/9/2021



Photo#1:

View of Location from entry to Southeast. Note Houndstongue plants along roadway.

June 9, 2021



Photo#2:

Exiting Location., view to Northwest. Note Houndstongue and white top along road and across location.

June 9, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Booco's PA Grassy Creek Coal API#107-06042



Photo#3:
Ruderal debris weeds, lack of desirable vegetation.



Photo#4:
Erosion on road at Southeast end of site.

June 9, 2021



Photo#5:
Erosion and undermining of root systems.



Photo#6:
Erosion and undermining of root systems.

June 9, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Booco's PA Grassy Creek Coal API#107-06042