

Inspection Photos
Operator: Paradox Upstream
API: 113-06235
Date: 6/9/2021



Photo 1. View the project area from the northeastern corner facing center.



Photo 2. View of the eastern fill slope from the northeastern corner facing southward. Revegetation is progressing with western wheatgrass, crested wheatgrass, and goldenaster.



Photo 3. View of musk thistles within the southern project area. Approximately 50 individuals observed.



Photo 4. View of reference area comprised of pinyon and juniper woodland mixed with sagebrush, James galleta, snakeweed, and goldenasters.