

**Inspection Photos**  
**Location Name: Frank J Vogl Nav #2**  
**Location ID: 318327**



**Photo 1 Well head**



**Photo 2 WH is LOTO**

**Inspection Photos**  
**Location Name: Frank J Vogl Nav #2**  
**Location ID: 318327**



**Photo 3 PU belts not attached.**



**Phot 4 PU electric motor has no power and has been removed from mounting brackets. Un able to operate.**



**Inspection Photos**  
**Location Name: Frank J Vogl Nav #2**  
**Location ID: 318327**



**Photo 5 electric breaker In the off position.**



**Photo 6 Electric meter has no power.**

**Inspection Photos**  
**Location Name: Frank J Vogl Nav #2**  
**Location ID: 318327**



**Photo 7 unmarked Not LOTO riser.**



**Photo 8 loc pic**



**Inspection Photos**  
**Location Name: Frank J Vogl Nav #2**  
**Location ID: 318327**



**Photo 9 Spindle Consolidation battery #6**



**Photo 10 Battery site GPS in photo.**