

# *Inspection Photos*

*API#107-06189*


*Operator: North Finn*

*Insp#: 692403487*

*Insp Date: 6/4/21*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:

Overview of Location to Northwest. Arrow indicates Wellhead. Two of eight anchors in foreground.

June 4, 2021



Photo#2: 2021

View of Associated lines, risers, Debris on Location .

June 4, 2021



Photo#3: 2020—better photo.

View of Associated lines, risers, Debris on Location .