

# *Inspection Photos*

*API#107-06206*

*Operator: North Finn*

*Insp#: 692403492*

*Insp Date: 6/4/21*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location to East.



Photo#2:  
Lines, risers, debris on Location

June 4, 2021





Photo#2:  
Four marked anchors & sign remain on site.



Photo#3:  
Lines, risers, debris on Location .

June 4, 2021