

Inspection Photos
Location Name: Arndt 27-30 HZ
Location ID: 457892



Photo 1 WH/sign



Photo 2 WH/sign

Inspection Photos
Location Name: Arndt 27-30 HZ
Location ID: 457892



Photo 3 WH/sign



Photo 4 WH/sign

Inspection Photos
Location Name: Arndt 27-30 HZ
Location ID: 457892



Photo 5 WH/sign

Photo 6 WH/sign

Inspection Photos
Location Name: Arndt 27-30 HZ
Location ID: 457892



Photo 7 WH/sign

Photo 8 WH/sign

Inspection Photos
Location Name: Arndt 27-30 HZ
Location ID: 457892



Photo 9 WH/sign

Photo 10 WH/sign

Inspection Photos
Location Name: Arndt 27-30 HZ
Location ID: 457892



Photo 11 TB signs



Photo 12 TB

Inspection Photos
Location Name: Arndt 27-30 HZ
Location ID: 457892



Photo 13 ECD



Photo 14 Horizontal Heated Separators

Location ID: 457892



Photo 15 Gas Meter Run




Photo 16 card in meter house indicates current calibration

Inspection Photos
Location Name: Arndt 27-30 HZ
Location ID: 457892



Photo 17 Compressors



Photo 18 FWKOs

Inspection Photos
Location Name: Arndt 27-30 HZ
Location ID: 457892



Photo 19 LACT

Photo 20 LACT

Inspection Photos
Location Name: Arndt 27-30 HZ
Location ID: 457892



Photo 21 pig station



Photo 22 ancillary equipment