

Inspection Photos
Location Name: Doris Ackerson unit #2
Location ID: 318233



Photo 1 loc pic. Weeds around well head and on location.



Photo 2 Well head sign not readable and weeds around equipment.

Inspection Photos
Location Name: Doris Ackerson unit #2
Location ID: 318233

