

Inspection Photos

API: 055-06189

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 6/16/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06189 | Date: 6/16/2021

Inspection Photos



Photo 1. Facing south along the former access road. The entire access road and location consists of noxious weeds; Red stem filaree.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06189 | Date: 6/16/2021

Inspection Photos



Photo 2. View of ground cover shows the weeds Redstem filaree and Alyssum.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06189 | Date: 6/16/2021

Inspection Photos



Photo 3. The access road disturbance is shown at right of red line and undisturbed is shown at left which consists of desirable vegetation (western wheatgrass).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06189 | Date: 6/16/2021

Inspection Photos



Photo 4. Facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06189 | Date: 6/16/2021

Inspection Photos



Photo 5. Facing east toward the location which consists of noxious weeds; Red stem filaree.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06189 | Date: 6/16/2021

Inspection Photos



Photo 6. Facing west toward the location which consists of noxious weeds; Red stem filaree.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06189 | Date: 6/16/2021