

Final Reclamation Inspection

June 16, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 322669

Inspection Document #: 697503016

Weld County, CO

SESE Section 4 T5N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: O'GRADY #2
Location ID: 322669



Photo 1. Photo taken from the southern well location, facing East. Photo illustrates well location meets Rule 1004 standards. No equipment was observed at the well location or associated offsite tank battery. The access road appears to be utilized for agricultural purposes and access to the irrigation system.

Inspection Photos
Location Name: O'GRADY #2
Location ID: 322669



Photo 2. Photo taken from the southern well location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: O'GRADY #2
Location ID: 322669



Photo 3. Photo taken from the southern well location, facing Northwest. See comments under Photo 1.